



Trouble codes

VCL  0.00V

P00AF72

Stored

Boost pressure control 'A' has a malfunction. The actuator does not close.



P029900

Stored

The boost pressure of turbocharger 1 is too low.



VIN:WDD2073032F181562

Info: Benz/207.303 - E
250 CDI BlueEFFICIENCY
Coupe / E 250 d Coupe

DTC
guide

Freeze
frame

Search

Erase
codes

Read
codes

ESC