



Address:
Postal address:
Phone:
Fax:
E-mail:
Homepage:

Mechanic:
Date: 7.10.2017
Car licence no:
VIN:
Mileage:
Vehicle: Mercedes - A-Class [W169] - 2005

Fault codes

Diesel (640.941 - CRA - MT/AT - 169.008/308)

DTC	Description
2251	- ESP activated; speed limit due to esp limp-home - Permanent
2242	- No or incorrect CAN message from control unit traction system hydraulic unit; plausibility - Permanent
2208	- CAN; brake signal plausibility - Permanent
2062	- Oil quality, level and temperature sensor, error in pulse monitoring of on/off ratio - Permanent

Brake (ESP (Electronic Stability Program) - ESP169 (Electronic Stability Program) - MT/AT)

DTC	Description
44A0	- Reversing light switch - Permanent
6560	- Emission test active - Intermittent

Multifunction (Central gateway (Gateway) - Central gateway (Gateway) - MT/AT)

DTC	Description
	No fault codes

Multifunction (DCM-FL (Door control module front left) - TSGVL169 - MT/AT)

DTC	Description
	No fault codes

Multifunction (DCM-FR (Door control module front right) - TSGVR169 - MT/AT)

DTC	Description
	No fault codes

Multifunction (DCM-RL (Door control module rear left) - TSGHL169 - MT/AT)

DTC	Description
	No fault codes

Multifunction (DCM-RR (Door control module rear right) - TSGHR169 - MT/AT)

DTC	Description
	No fault codes

Multifunction (Power steering - ES (Electrical power steering) - MT/AT)

DTC	Description
	No fault codes

Multifunction (SAM (Signal acquisition and control module) - SAM169 - MT/AT)

DTC	Description
	No fault codes

Multifunction (Steering wheel electronics - SCCM (Steering column module) - MT/AT)

DTC	Description
9000	- Control unit in steering wheel - Intermittent
